

## AIP SUPPLEMENT

TEL: 91-11-24632950 Extn: 2219/2233 AFS: VIDDYXAX FAX: 91-11-24615508 E_mail:- <a href="mailto:gmais@aaai.aero">gmais@aaai.aero</a>	AERONAUTICAL INFORMATION SERVICES AIRPORTS AUTHORITY OF INDIA RAJIV GANDHI BHAVAN SAFDARJUNG AIRPORT NEW DELHI - 110003	04/2008
		15 JANUARY 2008

File No. AAI/NAD/09-09/03/AIP-SUPP (Part-AIS)

Following supplement is issued for information, guidance and necessary action.


K. RAMALINGAM  
CHAIRMAN

AIRPORTS AUTHORITY OF INDIA

[Effective from 0803151800]

**SUB: COMMISSIONING OF NEW HYDERABAD INTERNATIONAL AIRPORT –  
RESTRUCTURING OF CONTROL ZONES.**

Control Zones of Hyderabad (HIAL) and Bidar has been restructured as follows:

Aerodrome	Hours UTC	Controlled Airspace Lateral Limits	Upper Limits	Language	Remarks
1	2	3	4	5	6
Hyderabad (HIAL)	H24	CTR bounded by coordinates 175543.6N 0775535.4E then along anticlockwise arc of 50NM centered at "HIA" VOR 171340.1N 0782420.9E to 175003.6N 0774755.5E to 174303.7N 0775355.5E then along the anticlockwise arc of 25NM radius with centred at 175503.6N 0772955.6E to 172838.7N 0773410.6E then along anticlockwise arc of 50NM centered at "HIA" VOR 171340.1N 0782420.9E to 175543.6N 0775535.4E.	FL100	EN	Airspace Classified Class "D"
Bidar	HO	CTR bounded by 174303.7N 0775355.5E then along the anticlockwise arc of 25NM radius centered at 175503.6N 0772955.6E to 175543.6N 0775535.4E then along anticlockwise arc of 50NM centered at "HIA" VOR 171340.1N 0782420.9E to 175003.6N 0774755.5E to 174303.7N 0775355.5	FL90	EN	Controlling Authority 'ATC Bidar' 123.5 Mhz.

AMEND AIP INDIA VTH EDITION ENR 2.2 ACCORDINGLY. DELETE CONTROL ZONE OF HYDERABAD FROM AIP INDIA VTH EDITION ENR 2.2 DATED 01 JAN 2006.